


LIBERTY BASE CASTING



DRAWN:	6/12/2015
CHECKED:	
REVISION:	DATE:
APPROVED:	
QUOTE:	
S.O.#:	
REF:	SCALE: NONE



SOME GEOGRAPHICAL AREAS HAVE SPECIAL WIND CONDITIONS THAT CAN CREATE WIND INDUCED VIBRATIONS CAUSING A FATIGUE PROBLEM. NO METHOD HAS YET BEEN FOUND FOR PREDICTING DESTRUCTIVE LIGHTING POLE VIBRATION. THESE CONDITIONS ARE UNIQUE AND CANNOT BE GUARANTEED AGAINST, AND ARE THE RESPONSIBILITY OF A LOCAL SITE ENGINEER.

TITLE: LIBERTY BASE CASTING	
CATALOG: LIB	
DWG NO: SD-7748	SIZE: C SHEET 1 OF 1